## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Applicant: Pillar et al.

Title: REFUSE VEHICLE CONTROL SYSTEM AND METHOD

Patent. No.: 7,412,307

Issue Date: 08/12/2008

Examiner: Broadhead, Brian J.

Art Unit: 3664

Conf. No.: 1930

## REQUEST FOR CERTIFICATE OF CORRECTION FOR PTO MISTAKE PURSUANT TO 37 C.F.R. § 1.322(a)

Commissioner for Patents

P.O. Box 1450

Alexandria, VA 22313-1450

Sir:

Enclosed is a Certificate of Correction, Form PTO/SB/44, for United States Patent Number 7,412,307 issued August 12, 2008. The following Patent Office printing error appears in the issued patent:

## IN THE CLAIMS

The location of the error in the claims of the issued patent is as follows:

Column 17,

line 31, before "in reverse" insert --is--.

Applicants submit that the above changes would not constitute new matter, and correction thereof would not require reexamination.

Pursuant to 37 C.F.R. §1.322, Applicants request that the enclosed Certificate of Correction be approved.

Although Applicants believe that no fee is required for this Request, the Commissioner is hereby authorized to charge any additional fees which may be required for this Request to Deposit Account No. 19-0741.

Respectfully submitted,

Date <u>8-27-08</u> By <u>/David G. Luettgen/</u>

FOLEY & LARDNER LLP Customer Number: 26371 Telephone: (414) 297-5769 Facsimile: (414) 297-4900 David G. Luettgen Attorney for Applicant Registration No. 39,282

MODIFIED PTO/SB/44 (04-05)

Approved for use through 04/30/2007. OMB 0651-0033 U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE

U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE
Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1950)

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 7,412,307 Page 1 of 1

APPLICATION NO. : 10/668,002

DATED : 08/12/2008

INVENTOR(S) : Duane R. Pillar; William M. Woolman

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 17,

line 31, before "in reverse" insert --is--.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Foley & Lardner LLP

777 E Wisconsin Avenue

Milwaukee, Wisconsin 53202-5306

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or rotation a brendit by the public which is to file (and by the USFI to) genome an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 how to complete, including gathering, preparing, and submitting the completed application form to the USFI CD. Time will vary depending upon the individual case. Any commenss on the amount of time vary unexpert to complete his form and/or application form to the USFI CD. Time will value due sent the individual case. Any commenss on the amount of time value unexpert to complete this form and/or applications of the USFI CD. Time will value due to the state of the USFI CD. Time will value the sent that the properties of the USFI CD. The USFI CD. Time value that the U

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.